



Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe

Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues

(Integrity, Construction and Lining) has been carried out.

38 Ardenlee Crescent

Certificate Reference

Certificate No:

Engineers Details								Insta	Installation Details						Client Details							
Trading Title		Jones Gas Services Limited							allation					Client		ir Belfast 2						
Address		8 Stanfield Row						Add	ress	38					Addres	S 1st FI	oor Carroll Ho					
		Belfast								Ardenlee Crescent						463a	Ormeau Road	b				
		County Antrim							Belfast						Belfast							
		Post Code: BT72HA								Post Code:							Post Code: BT7 3GR					
Gas Safe No:		567013 Telep			hone No: 077873		96692		Telephone N		No:			Telephone		e No: 4428902284		109				
Аp	ppliance De	Details							_	Insp				pection Details								
	Locatio	on	Appliance Type		Make		Model		Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO) (YIO = Vesual Improdor Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Kitche	Kitchen		ooiler	Ideal		LOGIC COMBI 24		0.0006	0.0006	25.6 kw	49	YES	RS	YES	YES	YES	YES	PASS	YES	YES	
2																						
3																						
4																						
5																						
oxdot	ults/Notes	s								Remedial Work Taken									Warning Notice Fixed			
1																						
2																						
3																						
4																						
5																						
Emergency Control Valve Accessible: YES Gas Tightness Satisfactory: YES										Signatures Gas ID Number:										4182771		
Gas Installation Pipework Visual Inspection Satisfactory: YES										_	ort Issued By: e: Gavin McAteer Signed:						Thu 00	Thu-09-02-2023				
Number of Appliances Tested: 1 Equipotential Bonding: YES										eceived By:						Date:	1110-09-	02-2023				
NEX	T INSPECTI BEFORE:		~ <u></u>	Fri-09-02-2024 Installation Pass: YES						enant	Уу.	Signed:					Date:	Thu-09-	02-2023			
CO Alarm fitted & working? YES Smoke alarm fitted & working? NA									_		This Gas S	afety Report w	fety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk									